

True to Compass

True Bearing	Leeway	Variation	Magnetic	Deviation	Compass

W+
E-

East is least
West is best

Compass to True

Compass	Deviation	Magnetic	Variation	Leeway	True Bearing

W-
E+